AUMINISTRATION Audinos Discussos DEPARTMENT OF BUILDING

Thomas F. Januaron

POINT OF SALE INSPECTION REPORT June 17, 2020

Location:

1439 Lander Road Mayfield Heights, OH 44124

Date of Inspection: Report Expires:

06/12/2020

Parcel Number: 861-13-076

Escrow Requirement:

\$15,000.00

Page 1 of 3

Owner Of Title:

James & Carol Jennings

Building Type: Single Family Dwelling

Mailing Address:

751 Cheriton Drive Highland Heights, OH 44143

Upon general Point of Sale Inspection of your property the following conditions were found to exist and are in violation of, Chapter 1339, Certificates of Inspection; Chapter 1381, General Provisions and Definitions, Chapter 1389, Basic Standards for Residential Occupancy; 1393, International Property Maintenance Code and all other applicable codes of the Codified Ordinances of the City of Mayfield Heights. You are hereby notified to correct the following:

| PM 302.3 | Install a hard surface driveway. Permit required. |
|-----------------|---|
| MHCO 1159.12 | Erect new code conforming garage. Permit required. |
| PM 304.7 | Replace roof of house at rear porch area. Permit required. |
| PM 304.15 | Replace rear entry door. |
| PM 304.6 | Replace damaged and or missing siding at front dormer. |
| PM 304,6 | Replace damaged and or missing siding at south side window. |
| PM 304.7 | Replace damaged or missing gutters. |
| PM 304.5 | Repair and tuckpoint foundation of house throughout. |
| PM 304.11 | Tuckpoint chimney and replace any missing bricks. |
| PM 302.3 | Replace multi-cracked or damaged concrete public sidewalk blocks. |

" A Vibrant Community"